








New Product Bulletin

Europe, Russia/CIS & Middle East Parts

November 2021

Part Number	Application	Cross-Ref.	Dimensions	Description	Associated Part Numbers*	Segment
 LF16450	Mercedes-Benz Sprinter II (906) (216, 316, 316 LGT/NGT, 516, 516 LGT/NGT) equipped with M271.951 engine	Mercedes (A)2711800109, (A)2711800009, (A)2711840125, (A)2711840225; M+H HU514X; Hengst E38HD106; Mahle OX1831DECO, OX1835D1; Ufi 2505000; Baldwin P40099;	H: 157,5 mm ID: 22 mm OD: 47 mm	Lube Filter, Cartridge Gasket ID: 17 mm Media Type: Cellulose	AF55735 (Cabin Air Filter), AF26462 (Cabin Air Filter, Activated Carbon), FF5006 (Fuel Filter), TF15074 (Transmission Filter)	
 FS20255	Fiat Ducato 2007 (2.0 JTD115; 2.3 JTD110, 120, 130, 150; 3.0 JTD180 Multijet Power); Fiat Fiorino 1.3 MultiJet 16V; Peugeot Boxer III (3.0HDI FAP180) (2011>); Citroen Jumper III (3.0HDI FAP 180) (2011>); Opel Combo D (X12) (1.3 CDTi; 1.6 CDTi; 2.0 CDTi)	Fiat 77363657; Citroën 1606384980, 1901A3; Ford 1729042, BS51-9155-A; Opel 818020; Vauxhall 95513399, 95514995; Peugeot 1606384980; M+H WK853/21; Hengst H340WK; Mahle KL567; Ufi 24ONE01	H: 205 mm OD: 84,5 mm	Fuel Water Separator	AF56063 (Cabin Air Filter), LF17472, LF17497 (Lube Filter, Spin On)	
 FF5956	Renault Trucks C & D-Series equipped with DTI8 & DTI5 engines; Volvo Bus B8R/B8RLE, 8900 & 9500 equipped with D8K engine; Volvo Trucks FE & FL-Series equipped with D8K & D5K engines Volvo Penta Engines TAD-Series;	Volvo 21746575; Renault 7421746573; Hengst E448KPD327	H: 126,7 mm ID: 86 mm OD: 86 mm	Fuel Filter, Cartridge Media Type: Cellulose	AF26415, AF26244 (Primary Air Filter), AF26464 (Cabin Air Filter), FS20112 (Fuel Water Separator), HF6162 (Steering Filter), AD27748 (Air Dryer), UF101 (Urea Filter)	 

* Partial list of associated parts included here. For full list, please visit our online catalog.

Replaced and/or obsoleted parts

Part number	Replacement PN
3896701	No replacement
3936770	No replacement
AF25641	No replacement
AF26575	No replacement
AF4804	No replacement
AF55743	No replacement
AK55690	No replacement
AK55691	No replacement
AS2220	No replacement
AS2221	No replacement
AS2288	No replacement
AS2409	No replacement
AS2447	No replacement
FF245	No replacement
FF5048	No replacement
FF5185	No replacement
FF5661	No replacement
FF5667	No replacement
FF5875	No replacement
FH23131M	No replacement
FS19572	FS19862
FS19585	FS19836
FS19729G	FS19729
FS19730G	FS19730
FS19761G	FS19761
HF28762	No replacement
HF28870	No replacement
HF29051	No replacement
HF30100	No replacement
HF30288	No replacement
HF30296	No replacement
HF30319	No replacement
HF35132	No replacement
HF40025	No replacement

Part number	Replacement PN
HF6851	No replacement
HF7008	No replacement
HF7021	No replacement
HF8081	No replacement
LF16212	No replacement
LF16215	No replacement
LF16220	No replacement
LF16277	No replacement
LF3731	No replacement
LF3896	No replacement
SP1019	No replacement
SP1020	No replacement
TF15016	No replacement
TF15068	No replacement
TF15070	No replacement
TF15077	No replacement