







New Product Bulletin

Europe, Russia/CIS & Middle East Parts

March 2022

Part Number	Application	Cross-Ref.	Dimensions	Description	Associated Part Numbers*	Segment
 AF56109	DAF, new CF trucks equipped with DAF MX11, MX13 and PX7 (Euro 6) engines, DAF, new XF trucks equipped with DAF MX11 and MX13 (Euro 6) engines	DAF 2181325, 2181324; M+H CU16003-2	H: 22 mm L: 156 mm W: 64 mm	Cabin Air Filter (set of two filters)	AF27972, AF4247 (Primary Air Filter) AF56009 (Cabin Air Filter, Active Carbon) FS19769 (Fuel Water Separator) LF17527, LF16015 (Lube Filter) HF6162, HF35489 (Steering Filter) UF101, UF106 (Urea Filter) AD27746 (Air Dryer)	
 FF42137	Mercedes-Benz Sprinter III (907, 910) (2018>) (211 CDI/214 CDI/311 CDI/314 CDI/411 CDI/414 CDI) equipped with OM651.950; Vito III (447) (2014>) (114 CDI/116 CDI/119 CDI BlueTEC) equipped with OM651.950	Mercedes Benz (A)6510903252, (A)6510902052; M+H WK820/20; Hengst H408WK; Mahle KL950; UFI 2419400; Wix WF8500; Bosch F026402842; Purflux FCS929	H: 100 mm OD: 87 mm	In-Line Fuel Filter	AF26375 (Panel Air Filter) AF56107, AF56086 (Cabin Air Filter) FF5862, FF5860 (In-Line Fuel Filter) LF4000 (Lube Filter)	
 FS20286	Citroën Jumper III (3.0 Hdi FAP 180) (2011>); Fiat Ducato 2007 (2.0 JTD 115 Multijet, 2.3 JTD 110/120/130/150/180 Multijet, 3.0 JTD 180 Multijet Power); Peugeot Boxer III (3.0 Hdi FAP 180) (2011>)	Citroën & Peugeot 1610192280, 1614157280; Fiat 77366565, 1371439080, 77367412; M+H WK9053Z; Hengst H446WK; Mahle KL977(D); UFI 24ONE0B	H: 195 mm OD: 84.5 mm	Fuel/ Water Separator	AF4440 (Primary Air Filter) AF56063, AF56062 (Cabin Air Filter) FS20255 (Fuel Water Separator) LF17472, LF17497 (Lube Filter, Spin-On)	

* Partial list of associated parts included here. For full list, please visit our online catalog.

Parts from other regions =>

**Made to order products (lead time 6-8 weeks) and currently not available/not in inventory in Europe.
Subject to minimum order quantities (MOQ's) – pls. validate details with your Area Sales Manager.**



FS20289

Caterpillar Skid Steer Loaders 200-Serie; Excavators 300-Serie; Wheel-Type Loaders 900-Serie; Paving Compactors CB2.5, CB2.7, CB2.9 & CC2.6 (2017>) equipped with Cat C1.5 engine;
Caterpillar Asphalt Pavers AP300F & AP355F (2016>) equipped with Cat C3.3B engine

Caterpillar 363-5819;
Baldwin PF46049;
Wix WF10586

H: 140.1 mm
ID: 26.2 mm

Fuel/ Water Separator
Cartridge

AF26389 (Primary Air Filter)
AF25557 (Primary Air Filter, Magnum RS)
AF26390 (Secondary Air Filter)
AF25558 (Secondary Air Filter, Magnum RS)
FF5097 (In Line Fuel Filter)
LF3758 (Lube Filter, Spin On)



Replaced and/or obsoleted parts

Part number	Replacement PN
259214	no replacement
259218	no replacement
259250	no replacement
259311	no replacement
259317	no replacement
259319	no replacement
259334	no replacement
259373	no replacement
259375	no replacement
259387	no replacement
3304865	no replacement
3304868	no replacement
3309197	no replacement
3309438C	no replacement
3310553S	no replacement
3312925	no replacement
3312928	no replacement
3312933	no replacement
3312934	no replacement
3312942	no replacement
3312943	no replacement
3321580S	no replacement
3825408	no replacement
3835425	no replacement

Part number	Replacement PN
3841704	no replacement
3845969	no replacement
FF5682	no replacement
HF29053	no replacement
MK11012	no replacement
MK11013	no replacement
MK11014	no replacement
MK11023	no replacement
MK11032	no replacement
MK11053	no replacement
MK11057	no replacement
MK11215	no replacement
MK11267	no replacement
MK11277	no replacement
MK11368	no replacement
MK11437	no replacement
MK11443	no replacement
MK11446	no replacement
MK11498	no replacement
MK11584	no replacement
MK11593	no replacement
MK11632	no replacement
MK11651	no replacement
MK11726	no replacement

Part number	Replacement PN
MK11776	no replacement
MK11800	no replacement
MK11802	no replacement
MK11814	no replacement
MK11837	no replacement
MK11977	no replacement
MK12017	no replacement
MK12019	no replacement
MK12024	no replacement
MK12036	no replacement
MK12042	no replacement
MK12049	no replacement
MK12073	no replacement
MK12185	no replacement
MK12260	no replacement
MK12310	no replacement
MK12351	no replacement
MK12358	no replacement
MK12368	no replacement
MK12381	no replacement
MK12382	no replacement
MK12389	no replacement
MK12390	no replacement
MK12405	no replacement

Part number	Replacement PN
MK12411	no replacement
MK12438	no replacement
MK12441	no replacement
MK12450	no replacement
MK12473	no replacement
MK12557	no replacement
MK12560	no replacement
MK12588	no replacement
MK12639	no replacement
MK12641	no replacement
MK12672	no replacement
MK12683	no replacement
MK12685	no replacement
MK12693	no replacement
MK12696	no replacement
MK12758	no replacement
MK12759	no replacement
MK12770	no replacement
MK12775	no replacement
MK12850	no replacement
MK12952	no replacement
MK12961	no replacement
MK12995	no replacement
MK13009	no replacement

Part number	Replacement PN
MK13014	no replacement
MK13020	no replacement
MK13024	no replacement
MK13025	no replacement
MK13026	no replacement
MK13030	no replacement
MK13036	no replacement
MK13037	no replacement
MK13062	no replacement
MK13069	no replacement
MK13071	no replacement
MK13085	no replacement
MK13087	no replacement
MK13093	no replacement
MK13107	no replacement
MK13111	no replacement
MK13120	no replacement
MK13155	no replacement
MK13180	no replacement
MK13190	no replacement
MK13191	no replacement
MK13202	no replacement
MK13205	no replacement
MK13297	no replacement

Replaced and/or obsoleted parts (continued)

Part number	Replacement PN
MK13447	no replacement
MK13460	no replacement
MK13869	no replacement
MK13872	no replacement
MK13874	no replacement
MK13882	no replacement
MK13885	no replacement
MK13887	no replacement
MK13891	no replacement
MK13891	no replacement
MK13904	no replacement
MK13905	no replacement
MK13908	no replacement
MK13909	no replacement
MK13920	no replacement
MK1451	no replacement
MK1530	no replacement
MK1538	no replacement
MK1547	no replacement
MK1549	no replacement
MK31M	no replacement
MK33M	no replacement